

0-180° fittings

Fitting at an angle of up to 180°. The fitting is used where the machine guard needs to be set up at angles other than 90°.



Models

ARTICLES / DESCRIPTION	
	**T01-01** Fittings for creating corners up to 180º